

RISK MANAGEMENT REPORT

ТҮРЕ	Excavator - Large (20 Tonne +)
MAKE	Doosan
MODEL	DX235LCR
PRICING GROUP NUMBER	339H

Report Number	15313 20190620-1303
Date	20-Jun-2019
Created By	Nic Mclennan
Assessor	Nic Mclennan
Assist. Assessor(s)	
Completed By	Nic Mclennan
Owner	AB Equipment Limited
Assessment Purpose	Hire
State	NZ



TABLE OF CONTENTS

SECTION 1	IMPORTANT INFORMATION Contains information outlining the scope and any limitations applicable to this Risk Management Report
SECTION 2	MACHINE DETAILS Contains standard machine specifications and details of any extras fitted
SECTION 3	RISK ANALYSIS, RISK EVALUATION & RISK TREATMENT Contains details of the technique used to calculate risk ratings, time frame and risk treatments. Please refer to this information when reviewing and interpreting the information in section 4 & 5
SECTION 4	RISK TREATMENTS REQUIRED Contains detailed information regarding the risk treatments to be implemented including hazard, risk rating, time frame, relevant standards & legislative references
SECTION 5	RISK TREATMENTS IN PLACE Contains detailed information regarding the risk treatments in place including hazard, risk rating, relevant standards & legislative references
SECTION 6	IMAGES AND NOTES Contains images & any relevant information entered by the assessor





Pricing Group Number Assessed By Date

SECTION 1 IMPORTANT INFORMATION

This report generated by Plant Assessor™ © Online Safety Systems on Thursday, 20 Jun 2019 4:14 PM

This report pertains to this item of plant as it appeared on the day of inspection.

It is the responsibility of the hirer to conform with the instructions and information contained within this report. Any change in condition of this item of plant should be reported to the hire company immediately.

Any information relating to the standard features have been supplied via the manufacturer and should be used as a guide only until verified.

For further information regarding this report contact Online Safety Systems on 1300 72 88 52

SECTION 2 MACHINE DETAILS

		1. Manufacturers specified noise level dBA	103
		2. Ambient noise level dBA	
MACHINE DETAILS		3. Noise level - Operator position (high idle) dBA	71
	- NOISE TEST RESULTS	4. Noise level - Operator position (low idle) dBA	
	- NOISE TEST RESULTS	5. Noise level LHS dBA @ m (high idle)	
		6. Noise level Front dBA @ m (high idle)	
ЩЦ		7. Noise level RHS dBA @ m (high idle)	
		8. Noise level Rear dBA @ m (high idle)	
. 프	BUCKET	Standard bucket capacity, SAE rated (m3)	1.08
A I	BUCKET	Standard bucket width (mm)	1370
Σ	CAPACITIES	Fuel Tank Capacity (Litres)	320
		Dig depth to cut 2.44 m level bottom (mm)	
		Digging depth (mm)	6670
		Dump height (mm)	7955
		Ground clearance (mm)	480
	DIMENSIONS/WEIGHTS	Max depth of vertical wall (mm)	5350
	DIMENSIONS/WEIGHTS	Operating weight (kg)	24600
		Tailswing radius (mm)	1680
		Transport height (mm)	3080
		Transport length (mm)	9010
		Width (mm)	2990
	ENGINE	Engine Displacement (Litres)	5.89
		Engine Hours	
		Engine Make & Model	DOOSAN DL06
	ENGINE	Engine Number	
		Engine Power (kW@rpm)	124 kW (166 HP) at 1900 rpm
		Number of Cylinders	6
	EXTRAS	Spare spool for attachments? Yes/No	
		Quick Hitch Make	GEITH
	HITCH	Quick Hitch Model	QC80H1G3
		Quick Hitch Serial No.	
		Flow of main pumps (L/Min)	2 x 220.2
	HYDRAULICS	Hydraulic Oil Reservoir Capacity (Litres)	345
	HTDRAULICS	Pump Types	2 x VDP
		Relief valve pressure, main pumps (Bar)	343
	PLANT CLASSIFICATIONS	Class	Excavator
	PLANT CLASSIFICATIONS	Year	
		FOPS Compliance No.	ISO 10262 : 1998 (Level II) and SAE J1356
	SAFETY STRUCTURES	FOPS Serial No.	
		ROPS Compliance No.	ISO 12117-2:2008
		ROPS Serial No.	
	TRACKS	Track length on ground (mm)	3650
	INACIO		





Make Doosan

Model DX235LCR

Type Excavator - Large (20 Tonne +)

Pricing Group Number Assessed By Date 339H Nic Mclennar 20-Jun-2019

	Track pad width (mm)	600
TRANSMISSION	Speed (km/h)	5.8 / 3.1
	Arm breakout (kgf)	12300
WORK CAPABILITIES	Bucket breakout (kgf)	15200
WORK CAPABILITIES	Gradeability - Degrees/(%)	70%
	Reach @ ground level (mm)	9630
	Air Conditioning	
EXTRAS	Bucket - 600mm	Trenching Bucket
	Bucket - Tilt	





SECTION 3 RISK ANALYSIS / RISK EVALUATION

RIS	RISK ANALYSIS					
CONSEQUENCE					•	
		1. INSIGNIFICANT Dealt with by in house first aid	2. MINOR Treated by medical professionals, hospital out patients	3. MODERATE Significant non permanent injury overnight hospital stay	4. MAJOR Extensive permanent injury eg. Loss of fingers, extended hospital stay	5. CATASTROPHIC Death, permanent disabling injury eg. Loss of hand, quadriplegia
Likeli	A. Almost certain to occur in most circumstances	MEDIUM 8	HIGH 16	HIGH 18	CRITICAL 23	CRITICAL 25
\	B. Likely to occur frequently	MEDIUM 7	MEDIUM 10	HIGH 17	HIGH 20	CRITICAL 24
	C. Possibly and likely to occur at sometime	LOW 3	MEDIUM 9	MEDIUM 12	HIGH 19	HIGH 22
	D. Unlikely to occur but could happen	LOW 2	LOW 5	MEDIUM 11	MEDIUM 14	HIGH 21
	E. May occur but only in rare circumstances	LOW 1	LOW 4	LOW 6	MEDIUM 13	MEDIUM 15

LUATION	CRITICAL	Act immediately to mitigate risk. Implement risk treatment(s) in accordance with the risk treatment table below.
RISK EVA	HIGH	Act immediately to mitigate risk. Implement risk treatment(s) in accordance with the risk treatment table below. If the appropriate risk treatments are not immediately accessible establish interim risk treatment strategies. Permanent risk treatments must be implemented within one week.
	MEDIUM	Take reasonable steps to mitigate and monitor the risk. Implement risk treatment(s) in accordance with the risk treatment table below. Permanent risk treatments must be implemented within one month.
	LOW	Take reasonable steps to mitigate and monitor the risk. Implement risk treatment(s) in accordance with the risk treatment table below. Permanent risk treatments must be implemented within three months.

Selecting the most appropriate risk treatment option involves balancing the costs and efforts of implementation against the benefits derived, with regard to legal, regulatory and other requirements. (source AS/NZS ISO 31000:2009)

Eliminate Eliminate the risk source.		Eliminate the risk source.
RISKI	Substitute	Provide an alternative that is capable of performing the same task which is safer.
Engineering Provide or construct a physical barrier or guard.		Provide or construct a physical barrier or guard.
	Administration	Develop policies, procedures, practices and guidelines in consultation with employees to mitigate the risk. Provide training, instruction and supervision about the risk source.
Personal protective Provide personal protective equipment to protect the individual from the risk source.		Provide personal protective equipment to protect the individual from the risk source.





SECTION 4 RISK TREATMENTS REQUIRED

This section of the report pertains to hazards created by use of this item of plant which currently do not have risk treatments in place. The risk treatments recommended in this section have been developed based on relevant Australian Standards, health & safety legislation, the hierarchy of risk treatment in accordance with the guidelines set forth in AS/NZS ISO 31000 – Risk Management and various other sources. The recommended risk treatment measures must be developed, implemented and validated as effective prior to the operation, maintenance or testing of this item of plant. Treatments applied must be dated and initialled adjacent the recommendations. All operators must read and understand the entire contents of this section prior to operating this item of plant.

НА	ZARD(S)	Prelim. Risk Rating	Residual Risk Rating	Time Frame	Due Date	Date Rectified	Initial
		Rating	runng	Tranic		Rectified	

SECTION 5 RISK TREATMENTS IN PLACE

This section of the report pertains to risk treatments currently in place on this item of plant. This section must be read in conjunction with the safety section of the manufacturers handbook. All operators must read and understand the entire contents of this section prior to operating this item of plant. These treatments or equivalent must remain in place at all times whilst this item of plant is in operation.

	HAZARD(S)	Prelim. Risk Rating	Residual Risk Rating		
ELIVERY	CRUSHING	HIGH 22	MEDIUM 15		
Risk Treatments in Place: SWMS Loading/Unloading Ensure that all operators follow approved SWMS/SOP when loading and unloading this machine to and from a flat top truck or t tilt tray.					
	References: Work Health & Safety Act & Regulations-				
	CRUSHING	HIGH 22	MEDIUM 15		
	Risk Treatments in Place: SWMS Load Restraint Ensure that all operators follow the approved SWMS/SOP when restraining this machine for	transport.			
	References: Work Health & Safety Act & Regulations-				
NOL		CRITICAL 24	MEDIUM 15		
OPERATION	Risk Treatments in Place: Operator Competency Only persons who are qualified, trained and experienced and/or hold the relevant certification/license can operate this item of plant. If there is not a competent/licensed person available for operation of this item of plant then only persons who are supervised by a competent/licensed person can operate this item of plant.				
	References: Work Health & Safety Act & Regulations-				
		HIGH 22	MEDIUM 15		
	Risk Treatments in Place: Operation Handbook The manufacturer's operation handbook has been supplied for this item of plant.				
	This handbook must be available at all times to all potential operators and supervisory staff. All potential operators must read and be familiar with this handbook prior to operating.				
	A complete risk assessment/Job Safety Analysis must be undertaken covering all operating processes and environments associated with this item of plant. SWMS should be produced for specific tasks associated with use of this item of plant.				





Make Doosan Model DX235LCR Type Excavator - Large (20 Tonne +) Pricing Group Number Assessed By Date 339H Nic Mclennar 20-Jun-2019

HAZARD(S)	Prelim. Risk Rating	Residual Risk Rating			
	HIGH 22	MEDIUM 15			
Risk Treatments in Place: Pre-op Checklist Excavator A pre-operation checklist is available for this Excavator. This checklist must be completed b	y all operators prior to operati	ng this Excavator.			
References: Work Health & Safety Act & Regulations-					
	HIGH 22	MEDIUM 15			
Risk Treatments in Place: SOP Excavator					
Safe Operation Procedures are available for this Excavator. The information in the Safe Op	eration Procedures must be fo	ollowed at all times whilst			
operating this Excavator.					
References: Work Health & Safety Act & Regulations-	1	1			
	HIGH 22	MEDIUM 15			
Risk Treatments in Place: Control Labels	·				
All controls including all levers, buttons, pedals, switches etc. are clearly labelled as to their	purpose and method of opera	ation. These labels must be			
maintained in a clean and serviceable condition at all times.					
References: AS/NZS4024.1905		1			
	HIGH 22	MEDIUM 15			
Risk Treatments in Place: Tank ID Label					
The tank(s) on this item of plant have clear, legible label(s) identifying their contents, and if		ntrols re: the contents.			
These must be present, clear and legible at all times. (this includes radiator, hydraulic and p	etrol/diesel tanks)				
References: Work Health & Safety Act & Regulations-	1	1			
INCORRECT OPERATION, CRUSHING	HIGH 22	HIGH 21			
Risk Treatments in Place: Boom Rated Capacity Label					
This item of plant has a rated capacity label fitted to each side of the boom. Ensure that the		at all times whilst this item			
of plant is in operation. Operators must not exceed this rated capacity at any time during op	eration.				
References: AS1418.8		1			
FIRE FIRE	HIGH 21	MEDIUM 15			
Risk Treatments in Place: Fire Extinguisher					
This item of plant is fitted with an approved and maintained fire extinguisher. Fire extinguish	., .	•			
They must be readily accessible to the operator. Regular inspections must also be carried of and AS 1851 – 1995	but in accordance with the mar	iufacturer's requirements			
	HIGH 21	MEDIUM 15			
Risk Treatments in Place: Quick Hitch Information					
This hydraulic quick hitch has the following information marked upon it -					
 A unique identification mark (serial number) The manufacturer's name and model clearly and durably marked upon it 					
3. The maximum rated capacity clearly and durably marked upon it					
4. The mass of the hitch clearly and durably marked upon it					
5. The lift point capacity (kg) clearly and durably marked upon it					
This information must be considered by all operators when assessing the suitability of the h this information could lead to serious injury or death.	itch for any task. Failure to co	nsider and or comply with			
References: AS4772					





	HAZARD(S)	Prelim. Risk Rating	Residual Risk Rating				
	COLLISION, STRIKING, CRUSHING	HIGH 19	MEDIUM 14				
The rear of t	Risk Treatments in Place: Tail Swing Label The rear of this item of plant has a hazard warning label re: general plant movement, tail swing, keep clear. It must be present and fully functional and serviceable at all times.						
	s: ISO20474-						
	CRUSHING	MEDIUM 15	MEDIUM 15				
	nents in Place: ROPS Label						
at all times.	label stating that the ROPS must not be damaged at any time (including cuts, d	Irill holes and welds) must be	present, clean and legible				
References	s: ISO3471						
00	BURNS, ENTANGLEMENT, SHEARING	MEDIUM 14	MEDIUM 13				
Risk Treatr	nents in Place: Engine Guard Label						
	an and alternator belts, pulleys and gears are guarded. These guards have clea						
	ds while engine is running. These labels must be present, legible and easily see s: AS1319- , AS/NZS4024.1201	en at all times whilst this item	of plant is in operation.				
References	S. AS1319-, AS/NZS4024.1201						
()	COLLISION, CRUSHING	MEDIUM 12	LOW 6				
Risk Treatr	nents in Place: Warning Device (horn)						
	plant is fitted with a fully functional audible warning device such as a horn. This y nearby pedestrians.	must be easily accessed by t	ne operator, and easily				
	should ensure the warning devices are functional at the start of each shift, by c cklists. Warning devices should operate automatically where appropriate (eg rev						
References	s: ISO7731, ISO9533						
	CRUSHING	CRITICAL 24	LOW 1				
	nents in Place: Closed Eye Lifting Point int fitted to this item of plant is the closed eye type. Hooks with or with out latchi	ing devices must not be used	as a lifting point at any				
References	s: AS1418.8						
*	STRIKING, BURNS	HIGH 22	MEDIUM 15				
This item of	Risk Treatments in Place: Hydraulic Hoses This item of plant has hydraulic hoses. These hoses must be inspected each day or before each use for wear and tear. If there are visible signs of wear immediate action must be taken to control the risk arising from this wear. These inspections must be documented.						
	Hydraulic fluid at high pressure can penetrate the skin, never use any part of your body to check for leaks. If oil penetrates the skin seek medical advice immediately. Always use a piece of cardboard or similar to check for suspected leaks.						
Hydraulic pre	Hydraulic pressure can be stored and is a hazard. Before disconnection or connection of hydraulic hoses complete the following steps -						
1. Stop engir	1. Stop engine						
2. Keep all b	ystanders clear of the work area						
	3. Refer to operators manual as to methods to release pressure						
4. Wait 5 mir							
References: AS2671, AS4024							





	HAZARD(S)	Prelim. Risk Rating	Residual Risk Rating
	CRUSHING, NON COMPLIANCE	HIGH 22	MEDIUM 15
The primar a) Must be	tments in Place: Control Lock out y operator controls are fitted with an isolation device which meets the following re engaged to allow entry & exit of the machine sily bypassed.	quirements -	1
plant. This device	deactivates the primary operator controls. This must be employed during entry, e must be fully functional at all times whilst this item of plant is in operation.	exit and while performing mai	ntenance on this item of
N	STRIKING, ENTANGLEMENT, COLLISION, CRUSHING	HIGH 22	MEDIUM 15
This item of	tments in Place: Neutral Start f plant has neutral start control in place. It must be fully functional and serviceable es: AS4024.1603	e at all times whilst this item c	of plant is in operation.
	CRUSHING	HIGH 22	MEDIUM 15
Risk Treatments in Place: Quick Hitch Controls The quick hitch operation control fitted with a device/method to prevent accidental operation. This device must be fully functional at all times whilst this item of plant is in operation.			
Reference	es: AS/NZS4024.1906, AS4772	1	1
	CRUSHING	HIGH 22	MEDIUM 15
This item of whilst this it	tments in Place: Seat Belt f plant is fitted with an operator seat belt. This seat belt must be free from damage em of plant is in operation. Operators must use this seat belt at all times during o es: ISO6683		lily attached at all times
	CRUSHING	HIGH 22	MEDIUM 15
The operate Operator se	tments in Place: Seat Belt or seat belt fitted to this item of plant must be fully functional and serviceable at a eat belts must be worn at all times whilst this item of plant is in operation. es: ISO6683	ll times. (N.B. It must not be a	attached to the ROPS).
	CRUSHING	HIGH 22	MEDIUM 15
This item of machine is	tments in Place: Quick Hitch Operation Alarm f plant is fitted with a quick hitch with a fully functional audible alarm fitted to the c in the mode that allows for the controls to be operated to engage or disengage at must be fully functional at all times whilst this item of plant is in operation.		e operator that the host
	es: AS4772, ISO7731		
	CRUSHING	HIGH 22	MEDIUM 15
An automat must be ful	tments in Place: Movement Awareness Alarm ic movement awareness alarm is fitted to this item of plant. This alarm is automa y functional and serviceable at all times whilst this item of plant is in operation. es: ISO7731, ISO9533	tically activated when travel in	n any direction occurs. It





HAZARD(S)	Prelim. Risk Rating	Residual Risk Rating	
CRUSHING	HIGH 22	MEDIUM 15	
Risk Treatments in Place: Quick Hitch - Fully Automatic This item of plant is fitted with a fully automatic hydraulic (quick) hitch (i.e. has hydraulically of controlled safety device as back up) between the excavator arm and attachments.	operated latch as primary rete	ention device and remotely	
This safety device must meet all of the following criteria at all times prior and during operatio	n -		
 Is a mechanical device i.e. not just an indicating system/device Must be intentionally disengaged to remove attachments Is not the primary source of retention of attachments Has means of verifying engagement of the primary retention device from the operator position and Has means of verifying engagement of safety system from operator position 			
If any of these criteria are not met at any time then operation must cease.			
References: AS4772			
COLLISION, POOR VISIBILITY	HIGH 22	MEDIUM 15	
Risk Treatments in Place: Machine Lights This item of plant is fitted with self contained lighting. All of these lights must be fully functional and serviceable whilst this item of plant is in operation in areas of reduced light. If any of these lights stop working the operation must cease immediately and the faulty light be repaired before operation can continue in the areas of reduced light. References: ISO20474-			
	HIGH 22	MEDIUM 15	
Risk Treatments in Place: Engine Guards The engine fan and alternator belts, pulleys and gears are guarded. These guards must be p whilst this item of plant is in operation.	present and fully functional an	d serviceable at all times	
References: AS/NZS4024.1601			
INSTABILITY, TIP OVER, CRUSHING	HIGH 22	MEDIUM 15	
Risk Treatments in Place: Levelness Device This item of plant is fitted with a level indicator. This device indicates the "levelness" of the machine chassis. During operation operators must ensure the machine is within the manufacturers guidelines for levelness. The rated capacity chart fitted for lifting operations has a maximum level angle which must never be exceeded during lifting operations. This level indicator must be present and fully functional at all times whilst this item of plant is in operation. References: AS1418.8			
±			
	HIGH 22	MEDIUM 15	
Risk Treatments in Place: Handrails All operator work platforms above 1.8 metres from the ground or nearest platform have an approved handrail. It must be present and fully functional and serviceable at all times. Handrails must meet the following requirements at all times whilst this item of plant is in operation - 1. All handrails are at least 0.95m 2. All handrails have a mid rail 3. All sides and ends have a kick plate which is at least 100mm high			
References: AS1657			





Ì

HAZARD(S)	Prelim. Risk Rating	Residual Risk Rating	
	HIGH 22	MEDIUM 15	
Risk Treatments in Place: Beacon This item of plant is fitted with a safety beacon. This beacon must meet the following criteria	at all times whilst this item of	plant fitted is in operation -	
 - Is visible up to 200m in all directions (allowing for intermittent obstruction from the plant str - Is fitted in the most appropriate location on machine to maximise visibility without risking controls 		veration)	
NOTE: more than one beacon may be fitted to meet these criteria.			
References: ISO20474-			
	HIGH 22	LOW 2	
Risk Treatments in Place: Plant Modification The plant is in original condition.			
	HIGH 21	MEDIUM 15	
Risk Treatments in Place: Windscreen Wipers		·	
The windscreen wipers and washers fitted to this item of plant must be fully functional at all References: AS/NZS4024.1201	times.		
ROPS FITTED CRUSHING	HIGH 21	MEDIUM 15	
Risk Treatments in Place: ROPS A Roll Over Protective Structure (ROPS) to ISO 3471, ISO 12117.1 or 2, AS 2294 or AS 4987 is fitted to this item of plant. A permanent label stating this standard must be attached to the structure at all times. This structure provides a safety envelope during a rollover. A warning label re: wearing of seat belts at all times whilst this item of plant is in operation and accordingly seat belts must be worn at all times during operation. References: AS2294, ISO3471			
CRUSHING	HIGH 21	LOW 5	
Risk Treatments in Place: FOPS Level II This item of plant is fitted with a level II Falling Objects Protective Structure (FOPS). This stu falling objects (e.g. trees, rocks). Care should still be exercised when operating in an area w	o 1	the operator from heavy	
References: AS2294, ISO3449, ISO10262		1	
	HIGH 20	MEDIUM 14	
Risk Treatments in Place: Intuitive Controls The controls fitted to this item of plant are orientated so that the movement of the control is consistent with the action of the machine e.g. moving a control lever to the left results in the machine turning to the left. This design feature must be maintained at all times whilst this item of plant is in operation. References: AS/NZS4024.1906			
STRAINS	HIGH 19	LOW 5	
Risk Treatments in Place: Controls Ergonomics All controls including all levers, buttons, pedals, switches etc, are placed near the operator work position and are easy to reach and operate during the execution of the operator's normal duties. This applies for all persons within the 95th percentile of the normal population distribution.			
References: AS/NZS4024.1901			
	HIGH 19	LOW 5	
Risk Treatments in Place: Hydraulic Hose Failure ShieldThis item of plant is fitted with a sturdy, permanent shield(s) between the hydraulic hoses and any body parts of the operator to provide protection during a hose or component failure. This shield(s) must be present and fully functional at all times whilst this item of plant is in operation.References:AS2671, AS4024, ISO4413			





MakeDoosanModelDX235LCRTypeExcavator - Large (20 Tonne +)

I

339H Nic Mclennan 20-Jun-2019

HAZARD(S)	Prelim. Risk Rating	Residual Risk Rating			
SLIPPING, INCORRECT OPERATION	HIGH 17	LOW 6			
Risk Treatments in Place: Control Levers/Pedals/Buttons					
All controls including all levers, buttons, pedals, switches etc. must be kept non-slip and fr	ee from damage at all times.				
References: AS/NZS4024.1901					
SLIPPING	MEDIUM 12	LOW 6			
Risk Treatments in Place: Operator Work Area Access/Egress Safe access and egress to the cabin/work area(s) must be maintained at all times whilst th from damage, located at a height so as to not cause undue body stresses and strains with					
 All personnel must - 1. Always face the item of plant during access and egress. 2. Always maintain three points of contact during access and egress. 3. Never carry an object(s) in his/her hand(s) during access and egress. 4. Never jump off machine. 					
References: AS3868		1			
SLIPPING, FALLING	MEDIUM 12	LOW 6			
Risk Treatments in Place: Access/Egress Instruction Label An instruction label is fitted adjacent access/egress areas to advise all personnel of the fo	lowing -				
 Always face the item of plant during access and egress. Always maintain three points of contact during access and egress. Ensure the steps are clean. Never jump off machine. 					
This label must be clear and legible at all times whilst this item of plant is in operation.					
References: ISO31000					
COLLISION, POOR VISIBILITY	ICANTSEE COLLISION, POOR VISIBILITY MEDIUM 12 MEDIUM 11				
Risk Treatments in Place: Operator Mirrors The operator rear view mirrors fitted to this item of plant must be fully functional and kept on each side to provide rear vision to the operator to avoid striking bystanders and objects		lways be at least one mirror			
References: ISO14401.1, AS/NZS4024.1201					
SLIPPING, FALLING, TRIPPING	MEDIUM 12	LOW 6			
Risk Treatments in Place: Engine Bay Access Safe access and egress to the engine bay/work area(s) must be maintained at all times whilst this item of plant is in operation. It must be non slip, free from damage, located at a height so as to not cause undue body stresses and strains with three points of contact available to personnel at all times.					
All personnel must - 1. Always face the item of plant during access and egress.					
 Always maintain three points of contact during access and egress. Never carry an object(s) in his/her hand(s) during access and egress. 					
4. Never jump off machine. References: AS3868					
BATTERY ELECTRIC SHOCK, BURNS	MEDIUM 12	LOW 6			
COVER Risk Treatments in Place: Battery Cover All batteries fitted to this item of plant are constrained to prevent displacement & fitted with a permanent sturdy cover which allows for ventilation.					
The constraint and cover must be present and fully functional and serviceable at all times whilst this item of plant is in operation. References: AS/NZS4024.1201					





Make Doosan

ModelDX235LCRTypeExcavator - Large (20 Tonne +)

	HAZARD(S)	Prelim. Risk Rating	Residual Risk Rating		
*	SLIPPING, INCORRECT OPERATION	MEDIUM 9	LOW 4		
	ttments in Place: Operator Floor ea floors are non-slip and free from damage & debris.	'	'		
Floor area	must remain non-slip and free from damage & debris, including rubbish, tools and	d other items, at all times whil	st this item of plant is in		
	es: AS/NZS4024.1201, ISO20474-				
Git	STRAINS	MEDIUM 9	LOW 1		
The opera	ttments in Place: Operator Seat tor seat fitted to this item of plant must remain free from damage and tears, and b	e permanently and securely fi	itted at all times.		
Reference	es: AS/NZS4024.1401 , ISO20474-	1	1		
	HEAT STROKE, DEHYDRATION	MEDIUM 9	LOW 4		
This item of also provid	ttments in Place: Air Conditioning of plant is fitted with an air conditioned cabin. This air conditioned cabin helps con- les shade from the sun. The air conditioner must be fully functional and serviceab es: ISO31000				
-~					
8	BURNS	MEDIUM 9	LOW 5		
The engine and fully fu	attments in Place: Exhaust e exhaust on this item of plant is fitted with a guard to prevent injury to any person inctional and serviceable at all times whilst this item of plant is in operation. es: AS/NZS4024.1201	and control the risk of initiati	ng a fire. It must be present		
*	CURRENT OR PREVIOUS STRUCTURAL DAMAGE	CRITICAL 25	MEDIUM 15		
Regular ch	Risk Treatments in Place: Structural Integrity Regular checks for structural damage must be undertaken. Look for cracks in frames/chassis (current or repaired), bends or damage to structural components, etc.				
*	INCORRECT OPERATION	HIGH 22	MEDIUM 15		
	ttments in Place: Maintenance Manual facturer's maintenance manual(s) has been supplied for this item of plant	1	I		
	These manual(s) must be available at all times to all users and maintenance staff of this item of plant. All users and maintenance staff must read and be familiar with these handbook(s) prior to maintaining or repairing this item of plant.				
A complete risk assessment/JSEA must be undertaken covering all inspection, maintenance, servicing and transportation requirements of this piece of plant prior to use.					
A full assessment of the competence of people using the book(s) must also be undertaken References: Work Health & Safety Act & Regulations-					
Ŷ	STRIKING, BURNS	HIGH 22	MEDIUM 15		
The hydra that hoses and prote	Risk Treatments in Place: Hydraulic Damage The hydraulic hoses to this item of plant are free from damage and protected against damage arising from contact with the plant structure. Ensure that hoses are free from damage and that protection is in place at all times whilst this item of plant is in operation. Inspection of the hydraulic hoses and protection system should be conducted regularly and documented as part of your plant safety programme. References: AS2671, AS4024, ISO4413				





	HAZARD(S)	Prelim. Risk Rating	Residual Risk Rat
	CRUSHING	HIGH 22	MEDIUM 15
Risk Treat	ments in Place: ROPS Damage	1	1
	er Protective Structure (ROPS) fitted to this item of plant must remain free from	damage at all times whilst this	s item of plant is in
operation.			
Reference	s: AS2294, ISO3471	1	1
V	OPERATIONAL MALFUNCTION	HIGH 22	LOW 2
Risk Treat	ments in Place: Major Fluid Leaks		
	plant must remain free from leaks at all times whilst in operation (this includes e		
	steering and hydraulics). Development of a major leak will require this item of p	lant to be stood-down until re	paired. Minor leaks
	ist be repaired within 1-14 days.		
Reference	s: ISO31000		
	OPERATIONAL MALFUNCTION	HIGH 21	MEDIUM 15
Service and These record includes the	ments in Place: Service Records maintenance records are available for this item of plant. ds must continue to be maintained and stored in a secure area as part of your p undertaking of regular inspections concerning the general condition of the item	of plant including (but not lim	ited to) tyre condition, o
Risk Treatu Service and These recom- includes the levels and w also be docu Reference	maintenance records are available for this item of plant. ds must continue to be maintained and stored in a secure area as part of your p undertaking of regular inspections concerning the general condition of the item year and tear on critical items such as brakes and steering, etc. All OEM prescrib umented as part of these records and attended to within a risk management fran s: Work Health & Safety Act & Regulations-	of plant including (but not limited, scheduled and non sche	ited to) tyre condition,
Risk Treatu Service and These recom- includes the levels and w also be docu Reference	maintenance records are available for this item of plant. ds must continue to be maintained and stored in a secure area as part of your p undertaking of regular inspections concerning the general condition of the item year and tear on critical items such as brakes and steering, etc. All OEM prescrib umented as part of these records and attended to within a risk management fram	of plant including (but not limited, scheduled and non sche	ited to) tyre condition,
Risk Treatu Service and These recom- includes the levels and w also be docu Reference	maintenance records are available for this item of plant. ds must continue to be maintained and stored in a secure area as part of your p undertaking of regular inspections concerning the general condition of the item year and tear on critical items such as brakes and steering, etc. All OEM prescrib umented as part of these records and attended to within a risk management fran s: Work Health & Safety Act & Regulations-	of plant including (but not limited, scheduled and non sche	ited to) tyre condition,
Risk Treatures and these recommendation of the second includes the levels and we also be docued and the second sec	maintenance records are available for this item of plant. ds must continue to be maintained and stored in a secure area as part of your p undertaking of regular inspections concerning the general condition of the item year and tear on critical items such as brakes and steering, etc. All OEM prescrib umented as part of these records and attended to within a risk management fran s: Work Health & Safety Act & Regulations- Comments: On request POOR VISIBILITY ments in Place: Windows & Screens cabin/work area safety glass windows and screens are kept clean and free from	of plant including (but not lim bed, scheduled and non sche nework. MEDIUM 9	LOW 4
Risk Treate Service and These recom- includes the levels and w also be docu Reference Assessor Risk Treate Ensure the oplant is in us	maintenance records are available for this item of plant. ds must continue to be maintained and stored in a secure area as part of your p undertaking of regular inspections concerning the general condition of the item year and tear on critical items such as brakes and steering, etc. All OEM prescrib umented as part of these records and attended to within a risk management fran s: Work Health & Safety Act & Regulations- Comments: On request POOR VISIBILITY ments in Place: Windows & Screens cabin/work area safety glass windows and screens are kept clean and free from	of plant including (but not lim bed, scheduled and non sche nework. MEDIUM 9	LOW 4
Risk Treate Service and These recom- includes the levels and w also be docu Reference Assessor Risk Treate Ensure the oplant is in us	maintenance records are available for this item of plant. ds must continue to be maintained and stored in a secure area as part of your p undertaking of regular inspections concerning the general condition of the item year and tear on critical items such as brakes and steering, etc. All OEM prescrib umented as part of these records and attended to within a risk management fran s: Work Health & Safety Act & Regulations- Comments: On request POOR VISIBILITY ments in Place: Windows & Screens cabin/work area safety glass windows and screens are kept clean and free from se.	of plant including (but not lim bed, scheduled and non sche nework. MEDIUM 9	LOW 4
Risk Treat Service and These recorr includes the levels and w also be docu Reference Assessor (Assessor (Ass	maintenance records are available for this item of plant. ds must continue to be maintained and stored in a secure area as part of your p undertaking of regular inspections concerning the general condition of the item year and tear on critical items such as brakes and steering, etc. All OEM prescrib umented as part of these records and attended to within a risk management fran s: Work Health & Safety Act & Regulations- Comments: On request POOR VISIBILITY ments in Place: Windows & Screens cabin/work area safety glass windows and screens are kept clean and free from se. s: ISO20474- , AS/NZS4024.1201 COLLISION, INSTABILITY ments in Place: Tracks and track components must be inspected as part of a "pre start" checklist. These	of plant including (but not lim bed, scheduled and non scher nework. MEDIUM 9 cracks and other damage at a MEDIUM 9	LOW 4

- No Images Available -

NOTES

IMAGES

- No Notes Available -







RISK MANAGEMENT REPORT

ТҮРЕ	Excavator - Large (20 Tonne +)	Report Number	15313 20190620-1303
MAKE	Doosan	Date	20-Jun-2019
MODEL	DX235LCR	Created By	Nic Mclennan
PRICING GROUP NUMBER	339H	Assessor	Nic Mclennan
	Assist. Assessor(s)		
		Owner	AB Equipment Limited
		Assessment Purpose	Hire
		State	NZ

OPERATOR ACKNOWLEDGEMENT

I the undersigned acknowledge that I have read and understand the risk management report described above.

I also acknowledge that I have received a copy of this risk management report.

DATE	NAME	COMPANY/POSITION	SIGNATURE



Thursday, 20 Jun 2019 4:14 PM

