

RISK MANAGEMENT REPORT

TYPE	Rollers, Smooth Drum Self Propelled
MAKE	Dynapac
MODEL	CA2500D

PRICING GROUP NUMBER HIREPOOL

Report Number	14584 20191121-0619
Date	25-Nov-2019
Created By	Zara Clifton
Assessor	Zara Clifton
Assist. Assessor(s)	John Dixon
Completed By	Zara Clifton
Owner	MIMICO
Assessment Purpose	Hire
State	NZ

TABLE OF CONTENTS

SECTION 1 IMPORTANT INFORMATION

Contains information outlining the scope and any limitations applicable to this Risk Management Report

SECTION 2

MACHINE DETAILS
Contains standard machine specifications and details of any extras fitted

contains claims opening and actual or any contact

SECTION 3 Contains details of the technique used to calculate risk ratings, time frame and risk treatments. Please refer to this information when reviewing and interpreting the information in section 4 & 5

RISK ANALYSIS, RISK EVALUATION & RISK TREATMENT

RISK TREATMENTS REQUIRED

Contains detailed information regarding the risk treatments to be implemented including hazard, risk rating, time frame, relevant standards & legislative references

RISK TREATMENTS IN PLACE

Contains detailed information regarding the risk treatments in place including hazard, risk rating, relevant

standards & legislative references

IMAGES AND NOTES

SECTION 6 Contains images & any relevant information entered by the assessor



SECTION 4

SECTION 5



SECTION 1 IMPORTANT INFORMATION

This report generated by Plant Assessor™ © Online Safety Systems on Monday, 9 Dec 2019 3:40 PM

This report pertains to this item of plant as it appeared on the day of inspection.

It is the responsibility of the hirer to conform with the instructions and information contained within this report. Any change in condition of this item of plant should be reported to the hire company immediately.

Any information relating to the standard features have been supplied via the manufacturer and should be used as a guide only until verified.

For further information regarding this report contact Online Safety Systems on 1300 72 88 52

SECTION 2 MACHINE DETAILS

S
⋖
\vdash
ш
ш
_
_
Ŧ
-
O
⋖
5

	Manufacturers specified noise level dBA	
	2. Ambient noise level dBA	
	3. Noise level - Operator position (high idle) dBA	
- NOISE TEST RESULTS	4. Noise level - Operator position (low idle) dBA	
- NOISE TEST RESULTS	5. Noise level LHS dBA @ m (high idle)	
	6. Noise level Front dBA @ m (high idle)	
	7. Noise level RHS dBA @ m (high idle)	
	8. Noise level Rear dBA @ m (high idle)	
BODY TYPE	Articulation, either side (deg)	38
BRAKES	Service Braking System	
CAPACITIES	Fuel Tank Capacity (Litres)	
	Ground clearance (mm)	
	Height (mm)	2870
	Length (mm)	5990
DIMENSIONS/WEIGHTS	Operating weight (kg)	11,900
DIMENSIONS/WEIGHTS	Static weight on drum (kg)	6300
	Turning circle diameter (mm)	5600
	Wheelbase (mm)	
	Width (mm)	2300
DRIVES	Drum drive	Yes
DRUMS	Drum width (mm)	2130
DRUMS	Static drum mass/lineal cm (kg)	26
	Engine Displacement (Litres)	4.5
	Engine Hours	
ENGINE	Engine Make & Model	Cummins QSB4.5 (IIIA/3 or IIIB/4i)
ENGINE	Engine Number	1
	Net power, SAE rated (kW@rpm)	119 kW (162.0 hp) @ 2,200 rpm
	Number of Cylinders	4
	Class	
PLANT CLASSIFICATIONS	Year	
TRANSMISSION	Transmission Type	Hydrostatic
TYRES	Tyre Size	
	Centrifugal force, high/low amplitude (kN)	250/130
WORK CAPABILITIES	Gradeability w/o vibration (%)	51
	Nominal amplitude, high+low (mm)	1.8/0.9
	Vibratory frequency, max+min (Hz)	33/34





SECTION 3 RISK ANALYSIS / RISK EVALUATION

RI:	SK ANALYSIS					
l ,≺	← CONSEQUENCE →					
LIKELIHOOD		1. INSIGNIFICANT Dealt with by in house first aid	2. MINOR Treated by medical professionals, hospital out patients	3. MODERATE Significant non permanent injury overnight hospital stay	4. MAJOR Extensive permanent injury eg. Loss of fingers, extended hospital stay	5. CATASTROPHIC Death, permanent disabling injury eg. Loss of hand, quadriplegia
LIKELI	A. Almost certain to occur in most circumstances	MEDIUM 8	HIGH 16	HIGH 18	CRITICAL 23	CRITICAL 25
↓	B. Likely to occur frequently	MEDIUM 7	MEDIUM 10	HIGH 17	HIGH 20	CRITICAL 24
	C. Possibly and likely to occur at sometime	LOW 3	MEDIUM 9	MEDIUM 12	HIGH 19	HIGH 22
	D. Unlikely to occur but could happen	LOW 2	LOW 5	MEDIUM 11	MEDIUM 14	HIGH 21
	E. May occur but only in rare circumstances	LOW 1	LOW 4	LOW 6	MEDIUM 13	MEDIUM 15

LUATION	Act immediately to mitigate risk. Implement risk treatment(s) in accordance with the risk treatment table below. Act immediately to mitigate risk. Implement risk treatment(s) in accordance with the risk treatment table below. If the appropriate risk treatments are not immediately accessible establish interim risk treatment strategies. Permanent risk treatments must be implemented within one week.	
SK E		
		Take reasonable steps to mitigate and monitor the risk. Implement risk treatment(s) in accordance with the risk treatment table below. Permanent risk treatments must be implemented within one month.
		Take reasonable steps to mitigate and monitor the risk. Implement risk treatment(s) in accordance with the risk treatment table below. Permanent risk treatments must be implemented within three months.

EATMENT		st appropriate risk treatment option involves balancing the costs and efforts of implementation against the benefits ard to legal, regulatory and other requirements. (SOUITCE AS/NZS ISO 3 1000:2009)		
REAT				
RISKT	Substitute	Provide an alternative that is capable of performing the same task which is safer.		
	Engineering	Provide or construct a physical barrier or guard.		
Administration Develop policies, procedures, practices and guidelines in consultation with employees to mitigate the risk Provide training, instruction and supervision about the risk source.		Develop policies, procedures, practices and guidelines in consultation with employees to mitigate the risk. Provide training, instruction and supervision about the risk source.		
	Personal protective Provide personal protective equipment to protect the individual from the risk source.			





SECTION 4 RISK TREATMENTS REQUIRED

This section of the report pertains to hazards created by use of this item of plant which currently do not have risk treatments in place. The risk treatments recommended in this section have been developed based on relevant Australian Standards, health & safety legislation, the hierarchy of risk treatment in accordance with the guidelines set forth in AS/NZS ISO 31000 - Risk Management and various other sources. The recommended risk treatment measures must be developed, implemented and validated as effective prior to the operation, maintenance or testing of this item of plant. Treatments applied must be dated and initialled adjacent the recommendations. All operators must read and understand the entire contents of this section prior to operating this item of plant.


HAZARD(S)	Prelim. Risk	Residual Risk	Time	Due Date	Date	Initial
HAZARD(3)	Rating	Rating	Frame	Due Date	Rectified	IIIItiai

SECTION 5 RISK TREATMENTS IN PLACE

This section of the report pertains to risk treatments currently in place on this item of plant. This section must be read in conjunction with the safety section of the manufacturers handbook. All operators must read and understand the entire contents of this section prior to operating this item of plant. These treatments or equivalent must remain in place at all times whilst this item of plant is in operation.

	HAZADD(C)	Drolim Dick Poting	Pacidual Biok Bating	
	HAZARD(S)	Prelim. Risk Rating	Residual Risk Rating	
IVERY	CRUSHING	HIGH 22	MEDIUM 15	
DELIV	Risk Treatments in Place: SWMS Loading/Unloading Ensure that all operators follow approved SWMS/SOP when loading and unloading this mad tilt tray.	chine to and from a flat top tru	ck or trailer, low loader or	
(References: Work Health & Safety Act & Regulations-			
	Assessor Comments: This is to be assessed by person authorizing the operator. No person shall operate unless qualified, trained, experienced and hold relevant licences.			
	CRUSHING	HIGH 22	MEDIUM 15	
	Risk Treatments in Place: SWMS Load Restraint Ensure that all operators follow the approved SWMS/SOP when restraining this machine for	transport.		
	References: Work Health & Safety Act & Regulations-			
NOI	NOMINATED OPERATION OPERATION ONLY	CRITICAL 24	MEDIUM 15	
Z	Risk Treatments in Place: Operator Competency			
OPERATION	Only persons who are qualified, trained and experienced and/or hold the relevant certification/license can operate this item of plant. If there is not a competent/licensed person available for operation of this item of plant then only persons who are supervised by a competent/licensed person can operate this item of plant.			

References: Work Health & Safety Act & Regulations-



Risk Treatments in Place: Operation Handbook

The manufacturer's operation handbook has been supplied for this item of plant.

This handbook must be available at all times to all potential operators and supervisory staff. All potential operators must read and be familiar with this handbook prior to operating.

A complete risk assessment/Job Safety Analysis must be undertaken covering all operating processes and environments associated with this item of plant. SWMS should be produced for specific tasks associated with use of this item of plant.





Make Dynapac Model CA2500D

Rollers, Smooth Drum Self Propelled

HAZARD(S) Prelim. Risk Rating **Residual Risk Rating INCORRECT OPERATION** HIGH 22 MEDIUM 15 Risk Treatments in Place: Pre-op Checklist Roller Smooth Drum Self Propelled A pre-operational checklist is available for this Roller, Smooth Drum Self Propelled. All operators must complete this checklist prior to operating this Roller, Smooth Drum Self Propelled. References: Work Health & Safety Act & Regulations-**INCORRECT OPERATION** HIGH 22 MFDIUM 15 Risk Treatments in Place: SOP Roller, Smooth Drum Self Propelled Safe Operation Procedures are available for this Roller, Smooth Drum Self Propelled. The information in the Safe Operation Procedures must be followed at all times whilst operating this Roller, Smooth Drum Self Propelled. References: Work Health & Safety Act & Regulations-**INCORRECT OPERATION** HIGH 22 MEDIUM 15 **=** 0 Risk Treatments in Place: Control Labels All controls including all levers, buttons, pedals, switches etc. are clearly labelled as to their purpose and method of operation. These labels must be maintained in a clean and serviceable condition at all times. References: AS/NZS4024.1905 CRUSHING HIGH 22 MFDIUM 15 Risk Treatments in Place: ROPS seat belt label This item of plant is fitted with a ROPS and has an advisory label stating that "seatbelts must be worn". This label must be present, clean and legible at all times. All operators and passengers must wear seatbelts whilst on this item of plant. References: AS2294, ISO3471 COLLISION HIGH 22 MEDIUM 15 ⚠ Risk Treatments in Place: Phone Use label This item of plant is fitted with an instruction label advising that mobile phones must not be used whilst operating this machine. Accordingly all operators must not use a mobile phone at any time whilst operating machine. If phone use is necessary then operator must place machine in park configuration in a safe position prior to phone use. Operators MUST adhere to this advice at all times. This label must be clear and legible at all times whilst this item of plant is in operation. References: AS1319-, ISO31000 POISONING, EXPLOSION, BURNS HIGH 22 MFDIUM 15 Risk Treatments in Place: Tank ID Label The tank(s) on this item of plant have clear, legible label(s) identifying their contents, and if appropriate any necessary controls re: the contents. These must be present, clear and legible at all times. (this includes radiator, hydraulic and petrol/diesel tanks)

References: Work Health & Safety Act & Regulations-



FIRE

HIGH 21


MEDIUM 15

Risk Treatments in Place: Fire Extinguisher

This item of plant is fitted with an approved and maintained fire extinguisher. Fire extinguisher(s) must be present and fully functional at all times. They must be readily accessible to the operator. Regular inspections must also be carried out in accordance with the manufacturer's requirements and AS 1851 – 1995







Risk Treatments in Place: Articulated Joint Crush Label

This item of plant has clear hazard warning labels re: crush zone, keep clear, that are attached to each side of the articulated joint. These must be present, clear and legible at all times whilst this item of plant is in operation.


References: ISO20474-, AS/NZS4024.1201



Risk Treatments in Place: Hearing Protection Label - Bystanders

The hazard warning labels re: wearing of hearing protection for bystanders attached to this item of plant refer to the level of noise produced. Permanent hearing damage will result if hearing protection is not worn. These labels must be present, clear and legible at all times whilst this item of plant is in operation.

References: AS/NZS1269, AS3781-



Risk Treatments in Place: Hearing Protection Label - Operator


The hazard warning label(s) re: wearing of hearing protection attached to this item of plant refer to the level of noise produced. Permanent hearing damage will result if hearing protection is not worn. These labels must be present, clear and legible at all times whilst this item of plant is in operation. References: AS/NZS1269, AS3781-



Risk Treatments in Place: Tail Swing Label

The rear of this item of plant has a hazard warning label re: general plant movement, tail swing, keep clear. It must be present and fully functional and serviceable at all times.

References: ISO20474-



Risk Treatments in Place: ROPS Label

The warning label stating that the ROPS must not be damaged at any time (including cuts, drill holes and welds) must be present, clean and legible at all times

References: ISO3471




BURNS, ENTANGLEMENT, SHEARING MEDIUM 14

MEDIUM 13

Risk Treatments in Place: Engine Guard Label

The engine fan and alternator belts, pulleys and gears are guarded. These guards have clear legible hazard warning labels re do not open or remove guards while engine is running. These labels must be present, legible and easily seen at all times whilst this item of plant is in operation.

References: AS1319-, AS/NZS4024.1201



Risk Treatments in Place: Warning Device (horn)

This item of plant is fitted with a fully functional audible warning device such as a horn. This must be easily accessed by the operator, and easily identifiable by nearby pedestrians.

All operators should ensure the warning devices are functional at the start of each shift, by completing pre-start checklists. Warning devices should operate automatically where appropriate (eg reversing)

References: ISO7731, ISO9533





HAZARD(S)	Prelim. Risk Rating	Residual Risk Rating
COLLISION	MEDIUM 9	LOW 5

Risk Treatments in Place: Recovery Point Label

This item of plant is fitted with a hazard warning label adjacent the recovery tow point which states "Recovery tow point – Read manufacturer's towing instructions before towing". Failure to do so could result in DEATH or SERIOUS INJURY.

This label must be clear and legible at all times whilst this item of plant is in operation.

References: ISO31000



COLLISION, CRUSHING

CRITICAL 24

MEDIUM 15

Risk Treatments in Place: Park Brake

This item of plant is fitted with a fully functional park (hand) brake which meets the following requirements –

- a) is separate to the service brakes
- b) has a device which maintains the brake in the on position until intentionally disengaged &
- c) requires at least two separate and distinct movements to disengage the park brake.

The park brake must be regularly inspected and tested. These inspections and tests must be documented as part of your plant safety programme.

References: AS2958



STRIKING, BURNS

HIGH 22

MEDIUM 15

Risk Treatments in Place: Hydraulic Hoses

This item of plant has hydraulic hoses. These hoses must be inspected each day or before each use for wear and tear. If there are visible signs of wear immediate action must be taken to control the risk arising from this wear. These inspections must be documented.

Hydraulic fluid at high pressure can penetrate the skin, never use any part of your body to check for leaks. If oil penetrates the skin seek medical advice immediately. Always use a piece of cardboard or similar to check for suspected leaks.

Hydraulic pressure can be stored and is a hazard. Before disconnection or connection of hydraulic hoses complete the following steps -

- 1. Stop engine
- 2. Keep all bystanders clear of the work area
- 3. Refer to operators manual as to methods to release pressure
- 4. Wait 5 minutes

References: AS2671, AS4024



STRIKING, ENTANGLEMENT, COLLISION, CRUSHING

HIGH 22

MEDIUM 15

Risk Treatments in Place: Neutral Start

This item of plant has neutral start control in place. It must be fully functional and serviceable at all times whilst this item of plant is in operation.

References: AS4024.1603



CRUSHING

HIGH 22

MEDIUM 15

Risk Treatments in Place: Seat Belt

This item of plant is fitted with an operator seat belt. This seat belt must be free from damage, and permanently and sturdily attached at all times whilst this item of plant is in operation. Operators must use this seat belt at all times during operation.

References: ISO6683



CRUSHING

HIGH 22

MEDIUM 15

Risk Treatments in Place: Seat Belt

The operator seat belt fitted to this item of plant must be fully functional and serviceable at all times. (N.B. It must not be attached to the ROPS). Operator seat belts must be worn at all times whilst this item of plant is in operation.

References: ISO6683






Make Dynapac Model CA2500D

Type Rollers, Smooth Drum Self Propelled

Pricing Group Number Assessed By Date HIREPOOL Zara Clifton 25-Nov-2019



A Roll Over Protective Structure (ROPS) to AS 2294, ISO 3471, ISO 12117.1 or 2 or SAE J1040 is fitted to this item of plant. A permanent label stating this standard must be attached to the structure at all times. It must also carry a warning label re: wearing of seat belts at all times whilst this item of plant is in operation, and accordingly seat belts must be worn at all times during operation.

References: AS2294, ISO3471



COLLISION, CRUSHING

HIGH 22

MEDIUM 15

Risk Treatments in Place: Reverse Movement Alarm

A reverse movement sensor alarm is fitted to this item of plant. It must be fully functional and serviceable at all times whilst this item of plant is in operation.

References: ISO7731, ISO9533



COLLISION, POOR VISIBILITY

HIGH 22

MEDIUM 15

Risk Treatments in Place: Machine Lights

This item of plant is fitted with self contained lighting. All of these lights must be fully functional and serviceable whilst this item of plant is in operation in areas of reduced light. If any of these lights stop working the operation must cease immediately and the faulty light be repaired before operation can continue in the areas of reduced light.

References: ISO20474-



ENTANGLEMENT

HIGH 22

MEDIUM 15

Risk Treatments in Place: Engine Guards

The engine fan and alternator belts, pulleys and gears are guarded. These guards must be present and fully functional and serviceable at all times whilst this item of plant is in operation.

References: AS/NZS4024.1601



CRUSHING

HIGH 22

MEDIUM 15

Risk Treatments in Place: Articulated Joint Locking Device

This item of plant is fitted with a safety locking device to the articulated joint (either a locking arm or cylinder locking devices) and clear, legible instruction labels on both sides of the articulated joint which state that either of these devices must be engaged during any maintenance to the articulated joint. These must be present, serviceable and employed at all times whilst this item of plant is in operation.

References: AS1319-, AS/NZS4024.1201



COLLISION

HIGH 22

MEDIUM 15

Risk Treatments in Place: Beacon

This item of plant is fitted with a safety beacon. This beacon must meet the following criteria at all times whilst this item of plant fitted is in operation -

- Is visible up to 200m in all directions (allowing for intermittent obstruction from the plant structure whilst the plant is in operation)
- Is fitted in the most appropriate location on machine to maximise visibility without risking continual damage

NOTE: more than one beacon may be fitted to meet these criteria.

References: ISO20474-



OPERATIONAL MALFUNCTION

HIGH 22

LOW 2

Risk Treatments in Place: Plant Modification

The plant is in original condition.





Make Dynapac Model CA2500D

Type Rollers, Smooth Drum Self Propelled

Pricing Group Number Assessed By Date HIREPOOL Zara Clifton 25-Nov-2019



Risk Treatments in Place: Two Operator Exits

The operator cabin/work area on this item of plant has a minimum of two (2) possible exits. These must be functional and accessible at all times whenever the item of plant is manned, whether during operation or maintenance activities.

References: AS5327



POOR VISIBILITY

HIGH 21

MEDIUM 15

Risk Treatments in Place: Windscreen Wipers

The windscreen wipers and washers fitted to this item of plant must be fully functional at all times.

References: AS/NZS4024.1201



INCORRECT OPERATION

HIGH 20

MEDIUM 14

Risk Treatments in Place: Intuitive Controls

The controls fitted to this item of plant are orientated so that the movement of the control is consistent with the action of the machine e.g. moving a control lever to the left results in the machine turning to the left. This design feature must be maintained at all times whilst this item of plant is in operation.

References: AS/NZS4024.1906



STRAINS

HIGH 19

LOW 5

Risk Treatments in Place: Controls Ergonomics

All controls including all levers, buttons, pedals, switches etc, are placed near the operator work position and are easy to reach and operate during the execution of the operator's normal duties. This applies for all persons within the 95th percentile of the normal population distribution.

References: AS/NZS4024.1901



STRIKING, BURNS

HIGH 19

LOW 5

Risk Treatments in Place: Hydraulic Hose Failure Shield

This item of plant is fitted with a sturdy, permanent shield(s) between the hydraulic hoses and any body parts of the operator to provide protection during a hose or component failure. This shield(s) must be present and fully functional at all times whilst this item of plant is in operation.

References: AS2671, AS4024, ISO4413



SLIPPING, INCORRECT OPERATION

HIGH 17

LOW 6

Risk Treatments in Place: Control Levers/Pedals/Buttons

All controls including all levers, buttons, pedals, switches etc. must be kept non-slip and free from damage at all times.

References: AS/NZS4024.1901



INCORRECT OPERATION, OPERATIONAL MALFUNCTION

MEDIUM 14

MEDIUM 13


Risk Treatments in Place: Restricted Access Switches

This item of plant is fitted with a device to restrict operators. A code/key must only be given to those that have appropriate experience or training.

References: AS/NZS4024.1201







Risk Treatments in Place: Operator Work Area Access/Egress

Safe access and egress to the cabin/work area(s) must be maintained at all times whilst this item of plant is in operation. It must be non slip, free from damage, located at a height so as to not cause undue body stresses and strains with three points of contact available to personnel at all times.

All personnel must -

- 1. Always face the item of plant during access and egress.
- 2. Always maintain three points of contact during access and egress.
- 3. Never carry an object(s) in his/her hand(s) during access and egress.
- 4. Never jump off machine.

References: AS5327



SLIPPING, FALLING

MEDIUM 12

LOW 6

Risk Treatments in Place: Access/Egress Instruction Label

An instruction label is fitted adjacent access/egress areas to advise all personnel of the following -

- 1. Always face the item of plant during access and egress.
- 2. Always maintain three points of contact during access and egress.
- 3. Ensure the steps are clean.
- 4. Never jump off machine.

This label must be clear and legible at all times whilst this item of plant is in operation.

References: ISO31000

or if you can't see my mirrors I CAN'T SEE

COLLISION, POOR VISIBILITY

MEDIUM 12

MEDIUM 11

Risk Treatments in Place: Operator Mirrors

The operator rear view mirrors fitted to this item of plant must be fully functional and kept clean at all times. There must always be at least one mirror on each side to provide rear vision to the operator to avoid striking bystanders and objects.

References: ISO14401.1, AS/NZS4024.1201



ELECTRIC SHOCK, BURNS

MEDIUM 12

LOW 6

Risk Treatments in Place: Battery Cover

All batteries fitted to this item of plant are constrained to prevent displacement & fitted with a permanent sturdy cover which allows for ventilation. The constraint and cover must be present and fully functional and serviceable at all times whilst this item of plant is in operation.

References: AS/NZS4024.1201



SLIPPING, INCORRECT OPERATION

MEDIUM 9

LOW 4

Risk Treatments in Place: Operator Floor

All work area floors are non-slip and free from damage & debris.

Floor area must remain non-slip and free from damage & debris, including rubbish, tools and other items, at all times whilst this item of plant is in use.

References: AS/NZS4024.1201, ISO20474-



STRAINS

MEDIUM 9

LOW 1

Risk Treatments in Place: Operator Seat

The operator seat fitted to this item of plant must remain free from damage and tears, and be permanently and securely fitted at all times.

References: AS/NZS4024.1401, ISO20474-





Make Dynapac Model CA2500D

Type Rollers, Smooth Drum Self Propelled

Pricing Group Number Assessed By Date HIREPOOL Zara Clifton 25-Nov-2019

Page 10 of 12

HAZARD(S)	Prelim. Risk Rating	Residual Risk Rating
HEAT STROKE, DEHYDRATION	MEDIUM 9	LOW 4

Risk Treatments in Place: Air Conditioning

This item of plant is fitted with an air conditioned cabin. This air conditioned cabin helps control the air quality and temperature for the operator and also provides shade from the sun. The air conditioner must be fully functional and serviceable at all times whilst this item of plant is in operation.

References: ISO31000



BURNS

MEDIUM 9

LOW 5

Risk Treatments in Place: Exhaust

The engine exhaust on this item of plant is fitted with a guard to prevent injury to any person and control the risk of initiating a fire. It must be present and fully functional and serviceable at all times whilst this item of plant is in operation.

References: AS/NZS4024.1201



COLLISION, CRUSHING

CRITICAL 25

MEDIUM 15

Risk Treatments in Place: Brakes

The brakes fitted to this item of plant must be fully functional at all times whilst this item of plant is in operation. The brakes must be regularly inspected and tested. These inspections and tests must be documented as part of your plant safety programme.

References: AS2958



CURRENT OR PREVIOUS STRUCTURAL DAMAGE

CRITICAL 25

MEDIUM 15

Risk Treatments in Place: Structural Integrity

Regular checks for structural damage must be undertaken. Look for cracks in frames/chassis (current or repaired), bends or damage to structural components, etc.



INCORRECT OPERATION

HIGH 22

MEDIUM 15

Risk Treatments in Place: Maintenance Manual

The manufacturer's maintenance manual(s) has been supplied for this item of plant

These manual(s) must be available at all times to all users and maintenance staff of this item of plant. All users and maintenance staff must read and be familiar with these handbook(s) prior to maintaining or repairing this item of plant.

A complete risk assessment/JSEA must be undertaken covering all inspection, maintenance, servicing and transportation requirements of this piece of plant prior to use.

A full assessment of the competence of people using the book(s) must also be undertaken

References: Work Health & Safety Act & Regulations-



COLLISION, INSTABILITY

HIGH 22

MEDIUM 15

Risk Treatments in Place: Tyres

The tyres and wheel components must be inspected as part of a "pre start" checklist. These inspections must be documented as part of your plant safety programme.

References: ISO31000



STRIKING, BURNS

HIGH 22

MEDIUM 15


Risk Treatments in Place: Hydraulic Damage

The hydraulic hoses to this item of plant are free from damage and protected against damage arising from contact with the plant structure. Ensure that hoses are free from damage and that protection is in place at all times whilst this item of plant is in operation. Inspection of the hydraulic hoses and protection system should be conducted regularly and documented as part of your plant safety programme.

References: AS2671, AS4024, ISO4413







Risk Treatments in Place: ROPS Damage

The Roll Over Protective Structure (ROPS) fitted to this item of plant must remain free from damage at all times whilst this item of plant is in operation.

References: AS2294, ISO3471



OPERATIONAL MALFUNCTION

HIGH 22

I OW 2

Residual Risk Rating

MEDIUM 15

Risk Treatments in Place: Major Fluid Leaks

This item of plant must remain free from leaks at all times whilst in operation (this includes engine, transmission, cooling system, air, fuel, drive line, wheel hubs, steering and hydraulics). Development of a major leak will require this item of plant to be stood-down until repaired. Minor leaks detected must be repaired within 1-14 days.

References: ISO31000



OPERATIONAL MALFUNCTION

HIGH 21

MEDIUM 15

Risk Treatments in Place: Service Records

Service and maintenance records are available for this item of plant.

These records must continue to be maintained and stored in a secure area as part of your plant safety management programme. This programme includes the undertaking of regular inspections concerning the general condition of the item of plant including (but not limited to) tyre condition, oil levels and wear and tear on critical items such as brakes and steering, etc. All OEM prescribed, scheduled and non scheduled maintenance must also be documented as part of these records and attended to within a risk management framework.

References: Work Health & Safety Act & Regulations-



POOR VISIBILITY

MEDIUM 9

LOW 4

Risk Treatments in Place: Windows & Screens

Ensure the cabin/work area safety glass windows and screens are kept clean and free from cracks and other damage at all times whilst this item of plant is in use.

References: ISO20474-, AS/NZS4024.1201

SECTION 6 IMAGES AND NOTES

IMAGES

- No Images Available -

NOTES

- No Notes Available -







RISK MANAGEMENT REPORT

TYPE	Rollers, Smooth Drum Self Propelled	Report Number	14584 20191121-0619
MAKE	Dynapac	Date	25-Nov-2019
MODEL	CA2500D	Created By	Zara Clifton
PRICING GROUP NUMBER	Hirepo0l	Assessor	Zara Clifton
		Assist. Assessor(s)	John Dixon
		Owner	MIMICO
		Assessment Purpose	Hire
		State	NZ

OPERATOR ACKNOWLEDGEMENT

I the undersigned acknowledge that I have read and understand the risk management report described above.

I also acknowledge that I have received a copy of this risk management report.

<u>DATE</u>	<u>NAME</u>	COMPANY/POSITION	<u>SIGNATURE</u>