

# Safe Operating Procedures

Make: Dynapac  
Model: CA2500D  
Type: Rollers, Smooth Drum Self Propelled  
Pricing Group Number: Hirepo0l



## Recommended PPE - Subject to Company & Site Policy



## SOP Roller, Smooth Drum Self Propelled

### GENERAL & START UP

- Read and understand manufacturers operational manual
- Complete pre-operational checklist (never use faulty or defective machinery)
- All operators must be free from the direct and after effects of drugs and alcohol
- Never operate in a poorly ventilated area, carbon monoxide is colourless, odourless and poisonous
- Ensure work area is clear of bystanders and hazards prior to starting engine and operating machine
- Once engine is started confirm control pattern and machine function
- Ensure that you are familiar with all attachments and the clearance distances between attachments and any other part of machine

### TRAVEL & OPERATION

- ! **ALWAYS** WEAR YOUR SEAT BELT
- ! **NEVER** USE PHONE WHILE OPERATING MACHINE
- ! **NEVER** CARRY PASSENGERS

- Ensure work area is clear of all bystanders
- Always consider ground type prior to travelling machine, use extreme caution on slippery surfaces such as metal, ice etc
- Never travel across slopes, travel up and down slopes only
- Refer to power line approach distance label re safety around power lines

### ROLL OVER HAZARD

- ! **NEVER** OPERATE MACHINE OVER "SHELF" ADJACENT EXCAVATION
- ! **NEVER** OPERATE MACHINE UNDER PRECIPICE OR OVERHEAD OBSTRUCTIONS
- ! **ALWAYS** USE EXTREME CAUTION WHEN OPERATING ADJACENT BATTER EDGE

- When stopping the roller: Park on even ground and lower any attachments to the ground. Shift the gear selector to park position and apply the parking brake. Turn off the ignition and remove the keys.

### TRANSPORT & MAINTENANCE

- ! **ALWAYS** SWITCH OFF ENGINE AND ENGAGE ARTICULATION LOCKING DEVICE PRIOR TO ANY MAINTENANCE OR TRANSPORTATION
- ! **ALWAYS** USE EXTREME CAUTION WHEN DRIVING ON & OFF FLOAT - ALWAYS HAVE A SECOND PERSON TO GUIDE YOU

### REFUELLING

- NEVER** refuel unless the engine is stopped and ignition turned off
- NEVER** smoke during refueling

### Operator Signature:

Name: \_\_\_\_\_ Date: \_\_\_\_\_ Signature: \_\_\_\_\_